

Fig. 3

Svmbol	Parameter	Typ.	Unit
Taz	Time to Acquire Zero	5	Seconds
Tio	Time to Initial Pressurization	09	Seconds
jd	Pressurization Initial	14.5	Inches H20
Tas	Time for Adiabatic Stabilization	09	Seconds
Tdonf	Time for Decay to Quick Pass / Fail	30	Seconds
þ	Pressure Final	14.5	Inches H2O
Tot	Time to Complete Test	155	Seconds

PEOEIVED 2002 2002 2800

COPY OF PAPERS ORIGINALLY FILED






Fig. 4

Symbol	rarameter	7	115
Taz	Time to Assume 7	32	Office
104	Unite to Actual e Cero	<u>ر</u>	Cocondo
Ë	Time to Initial Description	<u>,</u>	Seculds
2	I I I I I I I I I I I I I I I I I I I	<u></u>	Caronde
ä	Preserrization Initial		COLONS
		14.5	Inches H20
las	Time for Adiabatic Stabilization	80	7
Toons	, , , , , , , , , , , , , , , , , , ,	3	Spugge
idhn i	Time for Decay to Quick Pass / Fail	ער	Seconde
Dane		>	Springs
12.55	riessure Decay to Quick Pass / Fail	0.75	Inchae H2O
ă	Drocourt Class		110103 1120
	יומאסופ רווומו	14.5	Inches HOO
بن ۲	Time to Complete Tark	2	0.211631160
3	Tille to complete lest	130	Seconde
		.22	20000

JUL 3 0 2002 COPY OF PAPERS ORIGINALLY FILED TRADENA

	~ - å	COPY OF PAPER ORIGINALLY FILED PRADEMARY																	
Tg.		•	Unit	Seconds	Seconds	Inches H20	Seconds	Seconds	Inches H20	Seconds	Seconds	Seconds	Inches H2O	Seconds	Seconds	Seconds	Inches H20	Inches H2O	Seconds
Trp2 Trs2	Tdrt	Pdt	Тур.	5	09	14.5	09	20	0,75	2	30	20	1.5	10	30	40	1.5	13.0	280
Tip Trsi	Trpl	Taz Pdqpf Tct Pdrt	Parameter		Time to Initial Pressurization	Pressurization Initial	Time for Adiabatic Stabilization	Time for Decay to Quick Pass / Fail	Pressure Decay to Quick Pass / Fail	Time to Recover Pressure 1	Time to Recover Stability 1	Time for Decay Reference and Tank	Pressure Decay for Reference and Tank	Time to Recover Pressure 2	Time to Recover Stability 2	Time to Decay Tank	Pressure Decay Tank	Pressure Final	Time to Complete Test
			Symbol	Taz	Ţ	ā	Tas	Tdqpf	Pdqpf	Tro1	Trs1	Tdrt	Pdrt	Tro2	Trs2	Įğ	Pdt	Ď.	Tct

Fig. 5

SO STATE OF THE PROPERTY OF TH